ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	4	Yelahanka Satellite Town
Street ID	**Street Name**	**Significant Landmark**
W0226, W0162, W0231	NA	Chikkabommasandra
Segment No.	**Total Length (m)**	
4/S-W0226/S072233	121.27	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	2.87	77.580469	13.092033	77.580488	13.092015	W0162	W0162
2	118.40	77.580638	13.092206	77.581711	13.092007	W0253	W0231

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC drain at Chikkabommasandra cross roads in ward no 04 Yelahanka new Satellite town Sub-Division Yelahanka zone	1000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	DRAIN & CULVERT
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of RCC drain at Chikkabommasandra cross roads in ward no 04 Yelahanka new Satellite town Sub-Division Yelahanka zoneNote: - Construction of RCC drain in between 1st & 2nd Cross road	004-17-000043
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D)E-PMT-07/WO/47/2017-18	25/05/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
31/07/2017	30/07/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N SHIVAKUMARAA		0.00
Phone No.	**E-Mail ID**	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಬ.ಬ.ಎಂ.ಪಾ. ಬೆಂಗಳೂರು-106

9886650236

Inspection Details

Number of Trees	Any Other Information	Name
0		RAMANANJEEVAIAH

Date of Inspection	Remarks
27/08/2017	COMPLETED

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.

Zone: YELAHANKA Ward No: 4 Ward Name: Yelahanka Satellite Town Street ID: W0226, W0162, W0231

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106